

| Legend | |
|--------|--|
| ■ | Reported Coastal Flooding |
| ● | Reported Drainage Issues |
| ▲ | Reported Groundwater Flooding |
| ● | Reported Groundwater and/or Overland Flow Flooding |
| ★ | Reported Main River Flooding |
| ◆ | Reported Ordinary Watercourse Flooding |
| ◇ | Reported Overland Flow Flooding |
| * | Reported Sewer Flooding |
| ■ | Flood Zone 3 |
| ■ | Flood Zone 2 |
| — | Main River |
| — | Critical Ordinary Watercourse |

NOTES:


1) For Indication Only

2) The locations of reported flooding incidents are based on information from a variety of sources, and the accuracy of reported locations is variable. The reported flood locations shown are only intended to indicate that a reported flood event has occurred within or close to a settlement. This figure should not be relied upon to identify the location within the settlement where a reported event has occurred.

ARUP
Admiral House Rose Wharf
78 East Street Leeds LS9 9EE
Tel +44 (0) 113 242 9498
Fax +44 (0) 113 242 8573
www.arup.com

Job Title
**Northeast Yorkshire Strategic
Flood Risk Assessment**

Drawing Title
**Existing Flood Risk Situation
in Amotherby & Swinton**



| Job No. | Drawing No. | Status |
|---------|--------------|--------|
| 117775 | Figure 10.11 | ISSUE |